

## Town & River Lake Report

Inspection Date: March 10, 2025

### Technician's Comments:

Both cabinets checked and cleaned and filter switched. West cabinet needs a new compressor one is completely burnt out and not giving power to air stations as it should. Also recommend on getting some sound proof items for cabinet to not be so noisy.

