

Town & River Lake Report

Inspection Date: Jan 29, 2024

Technician's Comments:

East aeration cabinet - Cleaned cabinet, replaced dirty filter with a clean one. Compressor was unplugged and breaker was turned off. Turned breaker back on and plugged compressor back on, compressor is back on and working properly. All air stations are back on and working properly, diffusers are displaying correctly. Cabinet is in bad condition, will need to replace cabinet with a new noises cancellation cabinet and a new 4 piece manifold.

